| INDE | INDEX | | | | | | | | | | |
|------------|--|----------|--|--|--|--|--|--|--|--|--|
| Sr. No. | Particulars | Page No. | | | | | | | | | |
| 1. | Joint Committee Report in reference to OA No. 480 of 2022. | 1 | | | | | | | | | |
| 2. | Annexure-1 | 3 | | | | | | | | | |
| 3. | Annexure-2 | 8 | | | | | | | | | |

The Joint committee status report dated 28.10.2023 in compliance of Hon'ble NGT order dated 13.09.2023 in the matter of OA No. 480 of 2022 titled as Kuldeep Vs State of Haryana.

The Hon'ble NGT vide order dated 13.09.2023 directed that

- 5. The Joint Committee is directed to verify the factual position regarding compliance with consent conditions and environmental rules/norms/regulations by all the stone crushers operating in Birhi Kalan Zone and submit its report suggesting remedial measures and to send copies of its report to the concerned Statutory Authorities and also the Project Proponents for remedial action.
- 6. Additional report be filed by the Joint Committee on or before 31.10.2023by email at judicial-ngt@gov.in preferably in the form of searchable PDF/OCR Supported PDF and not in the form of Image PDF.
- 7. In case of violations the Joint Committee shall also put the concernedviolators to notice of the present proceedings pending before this Tribunal withspecific direction to appear before this Tribunal on the next date of hearingfixed hereinafter.

In compliance of NGT order dated 03.11.2022, the joint committee comprising of the SDM, Charkhi Dadri (Representative of Deputy Commissioner, Charkhi Dadri), Dr. Jitender Kumar, Deputy Director, Agriculture Department and Sh. Navneet Bhardwaj, AEE visited the stone crushers of Birhi Kalan, Charkhi Dadri in month of October 2023.

The compliance status of Air Pollution control measures provided on the stone crusher premises as per notification dated 11.05.2016 along with consent to operate status of stone crushing units of Birhi Kalan, Charkhi Dadri are enclosed as **Annexure-A**. Out of **30** nos of stone crushing units located in Birhi Kalan, Charkhi Dadri, **19** nos of stone crushing unit were found complying, **05** nos of stone crushing units have been dismantled and **06**nos of stone crushing units were found non complying due to inadequate air pollution control measures in the premises as per notification dated 11.05.2016.

Suggestion of remedial measures:

1. Closure action along with levy of Environment compensation on thenon-complying stone crushing units of Birhi Kalan, Charkhi Dadri be initiated by HSPCB.

(Action by: HSPCB)

2. The forest Department should carry out strip plantation on the route towards stone crushers of Birhi Kalan, Charkhi Dadri, with assistance of stone crushing units as required by the Forest Department.

(Action by: Forest Department)

3. Regular monitoring of stone crushing units of Birhi Kalan, Charkhi Dadri be carried out.

(Action by: HSPCB)

On behalf of the Joint Committee, the HSPCB will communicate the O6nos of violators (Annexure-B) to notice of the present proceedings pending before NGT with specific direction to appear before NGT on the next date of hearing fixed herein after.

Submitted for information and further necessary action please.

DA/ Annexure A & B

Ghrar, Dy Director Navneet Bhardwaj, AEE Dr Jite **HSPCB**

Agriculture, Ch. Dadri

NaveenKumar, HCS SDM, Charkhi Dadri

Annexure-A

| | Name of the Stone crusher | Consent to operate status | longitude | latitude | Production capacity (TPD) | Details | Covered | breaking wall/ Provision of telescopic | Status of metalled roads for vehicular movement within the premises. | wetting of the ground within the premises | periphery having avenue | Status of water sprinklers installed / storage of water for dust suppression | Status of sprinklers system/ inter locking system/separate energy meter/logbook details | Vehicle | e 01 | ompliance status Re Conditions of TO granted to ne unit | |
|-----|--|------------------------------------|------------|-----------|---------------------------------|---------|--|--|--|---|---|---|--|------------------------------|--------------------------------|---|---|
| | Baba Hari Dass Stone Crushing Co Vill-Birhi Kalan, Charkhi Dadri | 01.04.21- 31.03.26 | 76.140889 | 28.615755 | 1700 | 12K-0M | Non-Complying | Wind wall of 16feet height & 340 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 190 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 115 provided | Interlocking system of water spriknker system with stone crush machine provide | er | e ded | consent to operate end compling with conditions of consent to operate | CN for closure, levy of myronmental compensation and evocation of consent to perate issued to unit vide etter no. 913-14 dt. 10.10.2023 |
| 2 | Baba Raghu Nath Stone Crusher Vill-Birhi Kalan, Charkhi Oadri | 01.04.22- 31.03.27 | 76.139991 | 28.609568 | 100 | 12K-0M | Non-Complying | Wind wall of 16feet height & 370 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 250 Plants and I plantation obationed from DFO & same is verified by OFO | approx. 110 provided | interlocking system of wate spriknker syste with stone crus machine provide | m prov sher | | Unit is having valid consent to operate and compiling with conditions of consent to operate | SCN for closure, levy of environmental compensation and revocation of consent to operate issued to unit vide letter no. 972-73 dt. 23.10.2023 |
| 3 | Balaji Stone Crusher, Village Birhi Kalan, Charkhi Dadri | 01.04.21- 31.03.26 | 76.141384 | 28.614862 | 1500 | 20K-0M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 320 feet Length and telescopic chute about three feet below the wind breaking wall | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provide | Plants and | | er Interlocking system of wal spriknker syst with stone cr machine prod | ter - vel em pro usher | vered hicle ovided | Unit is having valid consent to operate and compling with conditions of consen to operate | <u>-</u> |
| | Chaudhary Stone Crusher Vill- Birhi Kalan, Distt Charkhi Dadri | Dismantled Plant & Machinery | 76.136005 | 28.6036 | | 12K-0M | - | provided | - | | | = | - | | | Dismantled Plant & | 266 |
| | Birhi Kalan, Charkhi Dadri | 01/04/2022 - 31/03/2027 | 76.141398 | 28.607425 | | | Non-Complying | Wind wall of 16feet height & 300 feet Length and telescopic chute about three feet below the wind breaking wall | Vehicular movement | Wetting & Cleaning of ti ground provi | Green belt of Plants and ded plantation obationed fr DFO & same verified by D | is | lying Interlocking system of w spriknker sy with stone machine pi | rstem crusher | Covered vehicle provided | Machinery | SCN for closure, levy of environmental compensation and revocation of consent to operate issued to unit vid letter no. 978-79 dt. |
| 6 0 | | 01.04.21- 31.03.24 | 76.1401165 | 28.607624 | 300 | 8K-4M | Unit has provided sheds with water sprinkler for dust suppression | provided Wind wall of | Vehicular movement | Wetting & Cleaning of ground pro | Green belt the Plants and vided plantation obtaioned DFO & sam verified by | approx. 1 provided from ne is | 20 system of | water System e Crusher | Covered vehicle provided | Unit is having vali consent to operat and compling wit conditions of con to operate | ne h |

| | | and the second | | | | | trespond to page them. | AND DESCRIPTION OF THE PARTY OF | 27 | | | | | | | |
|----|---|------------------------------------|-----------|-----------|------|--------|--|--|---|---|---|---|---|--------------------------------|--|--|
| 7 | Gitesh Stone Crusher Vill-Birhi Kalan,Distt Charkhi Dadri | 01/04/2022 - 31/03/2027 | 28.603857 | 76.138952 | 400 | 8K-OM | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 240 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalle d rou d provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 210 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 115 provided | Interlocking system of water spriknker system with stone crusher machine provided | | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 8 | Jagdish Pahal Stone Crusher Village Birhi Kalan Charkhi Dadri | 13.01.21- 31.03.26 | 76.138801 | 28.607937 | 2000 | 12k | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 260 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 330 Plants and plantation obationed from DFO & same Is verified by DFO | Water sprinker approx. 134 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 9 | Jai Baba Jamna Giri Stone Crusher, Vill. Birhi Kalan, Charkhi Dadri | Dismantled Plant & Machinery | 76.139411 | 28.607536 | • | • | - | - | - | - | - | - | - | - | Dismantled Plant & Machinery | - |
| 10 | | 01.04.22- 31.03.27 | 76.139411 | 28.607636 | 400 | 12k | Non-Complying | Wind wall of 16feet height & 320 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | ground provided | Green belt of 250 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 110 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | SCN for closure, levy of environmental compensation and revocation of consent to operate issued to unit vid letter no. 970-71 dt. 23.10.2023 |
| 11 | Jai Dada Budha Stone Crusher, Village Birhi Kalan, Charkhi Dadri | 01.04.21- 31.03.26 | 76.153726 | 28.599282 | 1700 | 24K-OM | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 300 feet Length and telescopic chute about three feet below the wind breaking wall orovided | Metalled road provided for Vehicular movement | Cleaning of the ground provided | | Water sprinker approx. 130 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | _ |
| 12 | Jai Hind Stone Crushing Co., Village Birhi Kalan, Charkhi Dadri | 01.04.21- 31.03.26 | 76.139633 | 28.605863 | 800 | 12K-0M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 180 feet Length and telescopic chute about three feet below the wind provided | Metalled road provided for Vehicular movement | Cleaning of the ground provided | Green belt of 170 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 95 provided | | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 13 | 301 111010 0 101111 | 01.04.21- 31.03.26 | 76.179315 | 28.533466 | 1800 | 15K-3M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 340 feet Length and telescopic chute about three feet below the wind breaking wall | Metalled road provided for Vehicular movement | Cleaning of the ground provided | Green belt of 470 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 165 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |



| 14 | Bishi Kalan, Charkhi Dadri | 0104.21- 31.03.24 | 28.608890 | 76.140060 | 400 | 8K | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 240 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 285 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 140 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | _ |
|----|--|------------------------------------|-----------|-----------|------|---------|--|--|--|---|---|---|---|--------------------------------|--|---------|
| | Mahadev Stone Crusher, Birhi Kalan, Chakrhi Dadri | 01.04.23- 31.03.28 | 76.138763 | 28.609674 | 1200 | 23K-12M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 290 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 380 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 115 proxided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 16 | Mahaluxmi Stone Crusher Village Birhi Kalan, Charkhi Dadri | 01.04.19- 31.03.24 | 76.139212 | 28.610786 | 550 | 18K-0M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 245 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 290 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 135 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | |
| 17 | Mayur Stone Crusher, Village Birhi Kala, Charkhi Dadri | 01.04.21 31.03.26 | 76.140478 | 28.608907 | 1700 | 12K | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 280 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Plants and | Water sprinker approx. 160 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 18 | N K Builders & Stone Crusher Vill-Birhi Kalan,Charkhi Dadri | Dismantled Plant & Machinery | 76.138952 | 28.598239 | | 16K-0M | | | | | | - | - | | Dismantled Plant & Machinery | 1 n = 1 |
| 19 | Neelkanth Mahadev Grit Udyog Vill-Birhi Kalan, Charkhi Dadri | 01/04/2022 - 31/03/2027 | 76.139804 | 28.604664 | 400 | 12K | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 320 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metailed road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 360 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 180 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 20 | New Rapid Stone Crusher old Name Jai baba Shyam Stone Crusher, Birhi kalan, Charkhi Dadri | 01/04/2022 - 31/03/2027 | 28.609588 | 76.139908 | 400 | 8K-0M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of 16feet height & 340 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 280 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 135 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |



| 71 | Purpal Stone Crusher, Village | las as as | | | | N. 1.31 1. | 200 100 600 | 0 | 0 | | | | | | |
|----|---|----------------------------|-----------|-----------|----------|--|--|--|---|---|---|---|--------------------------------|--|---|
| | Bishi Kala, Charkhi Dadri | 01.04.21- 31.03.26 | 28.608239 | 76.139470 | 1500 14K | sheds with water sprinkler for dust suppression | 16feet height & | Metalled road provided for Vehicular movement | Vetting & Cleaning of the ground provided | Green belt of 410 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 110 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | <u>.</u> |
| 23 | Kalan, Charkhi Dadri | Plant & | | | 8 | | | Metalled road provided for | Wetting & Cleaning of the | | | Interlocking system of water | Covered vehicle | Dismantled Plant & Machinery | |
| | Sangwan Stone Crusher, Vilalge Birhi Kalan, Charkhi Dadri | 19.12-19- 31.03.24 | 76.5464 | 28.84815 | 200 1: | K Unit has provide sheds with wate sprinkler for dus suppression | 16feet height & | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 297 Plants and plantation , obationed from DFO & same is verified by DFO | Water sprinker approx. 110 provided | Interlocking system of water spriknker system with stone crusher machine provided | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| | Shiv Shakti Grit Udyog, Village Birthi Kala, Charkhi Dadri | 01.04.21- 31.03.26 | 28.610259 | 76.139208 | 1800 2 | IK Unit has provide sheds with wate sprinkler for dus suppression | 16feet height & | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 595 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 125 provided | Interlocking system of water spriknker system with stone crusher machine provided | | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| | Shiv Shankar Stone Crusher Vill Birhi Kalan, Charkhi Dadri | 31.03.26 | 76.139016 | 28.604583 | 250 8K | OM Non-Complying | Non-Complying | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 280 Plants and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 140 provided | Interlocking system of water spriknker system with stone crusher machine provided | | Unit is having valid consent to operate and compling with conditions of consent to operate | SCN for closure, levy of environmental compensation and revocation of consent to operate issued to unit vide letter no. 974-75 dt. 23.10.2023 |
| 26 | Shiva Stone Crusher, Village Birhi Kalan, Charkhi Dadri | 06/05/2023 - 31/03/2028 | 76.139843 | 28.607476 | - 1: | | Wind wall of 16feet height & 350 feet Length and telescopic chute about three feet below the wind breaking wall provided | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 285 Plants and plantation obationed from DFO & same is verified by OFO | Water sprinker approx. 120 provided | Interlocking system of water spriknker system with stone crusher machine provided | | Unit is having valid consent to operate and compling with conditions of consent to operate | SCN for closure, levy of environmental compensation and revocation of consent to operate issued to unit vide letter no. 976-77 dt. 23.10.2023 |
| 27 | Shree Radhe Stone Crusher, Birhi Kalan, Charkhi Dadri | 25.07.19- 31.03.24 | 76.59641 | 28.84816 | 250 12K | OM Unit has provide sheds with wate sprinkler for dus suppression | d Wind wall of 16feet height & | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 560 trees and plantation obationed from DFO & same is verified by DFO | Water sprinker approx. 180 provided | Interlocking system of water spriknker system with stone crusher machine provided | | Unit is having valid consent to operate and compling with conditions of consent to operate | - |



| ** | | 31.03.26 | 76.265289 | 28.592062 | 2500 | | Unit has provided sheds with water sprinkler for dust suppression | 16feet height & 380 feet Length | Metalled road provided for Vehicular movement | Cleaning of the ground provided | | Water sprinker approx. 160 provided | system of water | Covered vehicle provided | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
|----|--|----------------------|-----------|-----------|------|--------|--|------------------------------------|--|---|---|---|---|--------------------------------|--|---|
| | Swastik Stone Crusher, Village Birhi Kalan, Charkhi Dadri | 31/03/2027 | 28.607697 | 76.137811 | 1500 | 12K-0M | Unit has provided sheds with water sprinkler for dust suppression | Wind wall of | Metalled road provided for Vehicular movement | Wetting & Cleaning of the ground provided | Green belt of 385 Plants and plantation obationed from DFO & same is verified by DFO | approx. 120 provided | Interlocking system of water spriknker system with stone crusher machine provided | 1 | Unit is having valid consent to operate and compling with conditions of consent to operate | - |
| 30 | V K Stone Crushing Co Vill-Birh Kalan, Charkhi Dadri | Plant & Machinery | 76.1388 | 28.6098 | | 12K-0M | - | - | - | - | | 1 | - | - | Dismantled Plant & Machinery | • |

Annexure-B

| Sr No. | Name & address of the Stone crusher | Detail of notice issued to appear before NGT |
|--------|---|--|
| 1 | | Notice regarding appearing before Hon'ble NGT have been issued to unit vide letter no. 989-91dated 27.10.2023. |
| 2 | Chirag Stone Crusher, Village Birhi Kalan, Charkhi Dadri | Notice regarding appearing before Hon'ble NGT have been issued to unit vide letter no. 992-94 dated 27.10.2023. |
| 3 | Jai Baba Jamna Giri Stone Crusher, Vill. Birhi Kalan, Charkhi Dadri | Notice regarding appearing before Hon'ble NGT have been issued to unit vide letter no. 995-97dated 27.10.2023. |
| 4 | Baba Hari Dass Stone Crushing Co Vill-Birhi Kalan, Charkhi Dadri | Notice regarding appearing before Hon'ble NGT have been issued to unit vide letter no. 998-1000 dated 27.10.2023. |
| 5 | Shiv Shankar Stone Crusher Vill-Birhi Kalan, Charkhi Dadri | Notice regarding appearing before Hon'ble NGT have been issued to unit vide letter no. 1001-1003 dated 27.10.2023. |
| 6 | Shiva Stone Crusher, Village Birhi Kalan, Charkhi Dadri | Notice regarding appearing before Hon'ble NGT have been issued to unit vide letter no. 1004-1006dated 27.10.2023. |

