

**BEFORE THE NATIONAL GREEN TRIBUNAL
PRINCIPAL BENCH NEW DELHI**

**OA NO. 667/2018 (MAHENDRA SINGH VERSUS STATE
OF HARYANA AND ORS.) WITH OA NO. 679/2018
(TEJPAL VERSUS STATE OF HARYANA AND ORS.),
IN OA NO. 599/2019 (BISHAMBER SINGH VERSUS
STATE OF HARYANA AND ORS.)**

AS PER HON'BLE NGT ORDER DATED 20.09.2023

Date:-20.11.2023

Place:-Mahendergarh

Hon'ble NGT passed the following directions in order dated 20.09.2023 in OA No. 667/2018 (Mahendra Singh Versus State of Haryana and Ors.) with OA No. 679/2018 (Tejpal Versus State of Haryana and Ors.), in OA No. 599/2019 (Bishamber Singh Versus State of Haryana and Ors.): -

"11. The Learned Counsel appearing for State of Haryana has submitted that he will look into each of the I.A. relating to each of the stone crusher units which have been impleaded as respondents in these original applications and tabulate all the relevant information in a chart form including the compliance by each of the units in respect of the pollution norms, obtaining CTE/CTO, inter-se distance between the units and compliance of the environmental guidelines for stone crusher units.

12. Let the same be filed within a period of 08 weeks by e-mail at judicialngt@gov.in preferably in the form of searchable PDF/ OCR Support PDF and not in the form of Image PDF."

Action Taken Report of District Mahendergarh in compliance of Hon'ble National Green Tribunal, Principal Bench, New Delhi order dated 20.09.2023 in the matter of OA No. 667/2018 (Mahendra Singh Versus State of Haryana and Ors.) with OA No. 679/2018 (Tejpal Versus State of Haryana and Ors.), in OA No. 599/2019 (Bishamber Singh Versus State of Haryana and Ors.).

The stone crushers are located in the district of Mahendragarh, Haryana in the various villages of 03 Nos. of Tehsil namely i) Mahendragarh ii) Narnaul and iii) Nangal Chaudhary. There are total 133 Nos. stone crushing units in district Mahendragarh as per order of Hon'ble NGT since 2013. The Report in compliance with the above directions, passed by Hon'ble National Green Tribunal, New Delhi, is as under:-

1. In compliance of Order dated 20.09.2023, all the stone crushing units were inspected by the Officers of the HSPCB. Status of these 133 units are summarized below:

A.	Units found Complying as per provision of notification dated 11.05.2016	79
B.	Units found non-complying as per provision of notification dated 11.05.2016 and bifurcated as below:-	54
	(i). Units under Show Cause Notice issued by HSPCB for closure.	06
	(ii). Units closed by Board&CTE/CTO revoked by Board	23
	(iii). Units found dismantled	11
	(iv). Closed of its own	14

2. A total amount of Rs. 140.00 lacs (One Crore, Forty Lakhs) has been deposited by 07 Nos. of stone crusher of Rs. 20.00 lacs each as interim environmental compensation in the account of HSPCB, Panchkula as per order dated 18.01.2023 of Hon'ble NGT.
3. The requisite information of 133 stone crushing units in tabular form regarding status of compliance in respect of the pollution norms, CTE/CTO, inter-se distance between the units and the compliance regarding notification dated 11.05.2016 for stone crusher units is attached as **Annexure-1**.
3. All the stone crushing units of district Mahendragarh are presently lying closed in compliance of CAQM orderNo. 120017/27/GRAP 2021/CAQM dated 02.11.2023 & 05.11.2023 under Stage-III & Stage-IV.

It is, therefore, prayed that the above Report alongwith information in tabulate form in compliance with the directions issued by this Hon'ble Tribunal vide order dated 20.09.2023, may kindly be considered, please.

Dated :-20.11.2023


Regional Officer
HSPCB, Mahendragarh

Sr No.	Respondent No. (IA No.)	Name and address of the unit Latitude Longitude	Latest CTO status with validity	Inter-se distance (Distance of stone crusher nod to the boundary of nearest stone crusher)	Status of Covered shed/Dust containment cum suppressing system	Status of Provided Wind breaking wall/ Provision of telescopic chute.	Status of metalled roads for vehicular movement within the premises	Status of cleaning and wetting of the ground within the premises.	Status of Green belt along the periphery having avenue plantation of 2-3 rows/as per plantation plan approved by DFO.	Status of water sprinklers installed for dust suppression	Status of sprinklers system/ inter locking system/separate energy meter/logbook details.	Operational Status	Interim EC of Rs. 20.0 Lakhs deposited or Not	Remarks	Action Taken
1	12 (94-95 of 2023)	SHREE BALAJI GRIT UDYOG M.No. 23, Kila No. 9 (8-0), 2 min South (4-0), 8/2 min West (6-0), 13/1 min West (2-0), 12/1 (2-0), 12/2 (6-0) Total 28 Kanal 0 Marla at Village-Gangutana, Tehsil-Nangal, Chaudhary, Distt-Mohindergarh 27.877648 76.061147	Granted from 01/04/2021 - 31/03/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
2	13 (96-97 of 2023)	SHREE RAM STONE CRUSHER, M.No. 62, Kila No. 3 (7-12), 2/3 (1-17), 2/1 (1-12), 2/4 (2-16) and 2/2 (0-11) Total 14 Kanal 8 Marla at Village-Dholera, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.92501 76.06026	Granted from 29/11/2021 - 31/03/2026	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
3	14 (98-99 of 2023)	Shree Balaji Stone Crusher, M.No./Kila No 62/9(4-0), 7/2 (2-3)& 8(6-18), Village-Dholera, Tehsil-Nangal Choudhary, Distt-Mohindergarh 27.92264 76.06054	Granted from 01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	-	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

4	15 (106-107 of 2023)	ASHA STONE CRUSHING CO, Khwat No. 110, Khatoni No. 128, Mustil & Kila No. 62 / / 5/2(6-16), 6 Min west(5-18), 343/1 min west (0-14) total 13 Kanal 8 Marla VILLAGE DHULEDA NARNAUL MAHENDERGARH 27.922662 76.064052	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7729 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
5	16 (119 of 2023)	GANESH STONE CRUSHER Khewat No. 75, Khatoni No. 81, M.No. 8, Kila No. 23 (8-0) At Village-Khatoli Ahir, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.966494 76.083972	Granted from 01/04/2023 - 31/03/2028	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Deposited	Complying	NA
6	17 (121-122 of 2023)	SHRI RAM STONE CRUSHER PLANT 2, Khewat No. 23, Khatoni NO. 25, M./Kila No. 46//21 (8-0), 22(8-16), 48//1(7-7) & 2(2-11) total 26 Kanal 14 Marla at Village Panchnota, Nangal Chaudhary, Distt-Mohindergarh 27.903847 76.017596	Granted from 14/10/2020 - 31/03/2024	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
7	18 (123-124 of 2023)	Baba Kheta Nath Stone Crusher, Kila No. 109/2/1, 9/1, 98/22/2, 8 kanal 16 marla 98/22// 5 kanal 0 marla total 13 kanal 16 marla Vill.- Zerpur, M/garh 28.324268 76.087004	Granted from 26/12/2022 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

8	19 (271-272 of 2023)	SATYAM STONE CRUSHER UNIT II MUSTKIL NO 57 KILLA NO. 12/2/1 & 19/2, VILLAGE BEGOPUR TEHSIL NARNUAL 27.92374 76.05472	Granted from 01/10/2021 to 31/03/2026	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7730 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
9	20 (273-274 of 2023)	Siddhi Vinayak Stone Crusher Vill-Dholera, Narnaul, Distt-Mohindergarh Khewat No. 361, Khatoni No. 400, M.No. 51, Kila No. 19/2 (6-12) & Khewat No. 365, Khatoni No. 409, M. No. 51, Kila No. 22 (1 -15) total measuring 8 K 7 M MAHENDRAGARH 27.924129	Granted from 01/10/2021 to 30/09/2026	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
10	21 (275-276 of 2023)	Mahalaxmi Stone Crusher, Khewat No. 197, Khatoni No. 231, Kila No. 50/16/2, 6/15, Vill-Dholera, Nangal Chaudhary, Mohindergarh 27.924626 76.05945	Granted from 01/04/2022 - 31/03/2027	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
11	22 (277-278 of 2023)	Rajokari Stone Cr. (Kontech Crushing Co.,) Khewat no. 16, khatoni no. 46 & 48, rakba 140 kanal & 16 Marla, khasra no. 7//21 (8-0), 22 (7-1) & 8//25/2 (5-12) Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.920515 76.054241	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

12	23 (279-280 of 2023)	JAI BHARAT STONE CRUSHER Khewat No. 107, Khatoni No. 121, M.No. 53, Kila No. 23 Min East (4-0) & 24 (8-0) Total 12 Kanal 0 Marla at Village-Begopur, Nangal Chaudhary, Distt-Mohinergarh 27.925918 76.051751	Granted from 22/04/2021 - 31/03/2025	55 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7731 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Not Complying	Show Cause Notice issued for the non-compliance observed
13	24 (281-282 of 2023)	Nirvaan Infrastructure At Khewat No. 143, Khatoni No. 170, M.No. 13, Kila NO. 17(8-0), 18(8-0), 19(5-14) & 24/1 (2-0) (Total 23K-14M), Vill-Lutafpur, Terhsil-Narnaul Distt-Mohindergarh 28.04342 76.05209	Granted from 01/04/2023 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
14	25 (283-284 of 2023)	Sheranwali Stone Crusher, Khewat No. 25, Khatoni No. 54, total 45 kanal 9 marla Vill-Bakhrija, Narnaul, Distt. Mohindergarh 27.92022 76.053868	Granted from 01/04/2023 - 31/03/2028	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
15	26 (285-286 of 2023)	Shree Shyam Stone Crusher, Khewat No. 237, Khatoni No. 269, Kila No. 51 / / 13, (8-0), 17/3/3 (3-16), 18(8-0), 19/1 (0-2)Vill-Dholera, Nangal Chaudhary, Distt-Mohindergarh 27.9243 76.061297	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

16	27 (287-288 of 2023)	Satyam Stone Crusher, Khewat no. 182, khatoni no. 209, kila no. 57/12/2, 13/2, 18,19/1, 19/2 (19 kanal) Vill-Begopur, Narnaul, Distt-Mohindergarh 27.92374 76.05472	Granted from 01/04/2022 - 31/03/2027	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7732 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
17	28 (320-321 of 2023)	SHRI RADHEY MINES PRIVATE LIMITED, Khewat No. 10, Khatoni NO. 13, M.No. 8, Kila No. 23 (2-0), 24 Min South (2-18) & M.No. 13, Kila No. 4/1 (7-2) total 12 Kanal 0 Marla at Village-Gangutana, tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.86639 76.04743	Granted from 25/07/2020 - 31/03/2024	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
18	29 (393-394 of 2023)	SHRI RAM STONE CRUSHER, Khewat No. 11, Khatoni NO. 11, M.No. 49, Kila No. 3 (7-11) & 4 (7-11) total 15 Kanal 02 Marla at VIII-Panchnota, Nangal Chaudhary Distt-Mohindergarh 27.904775 76.017043	Granted from 30/07/2019 - 31/03/2024	80 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
19	30 (694-695 of 2023)	Haryana stone crusher Kila NO. 25//19,20, Vill: garhi distt. Mahendergarh 28.434106 76.111652	Granted from 31/10/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

20	31 (696-697 of 2023)	Shree Baba Jairamdass Grit Udyog, Khewat No. 5, Khatoni No. 15, Kila No. 35, total 206 kanal 4 marla Vill-Garhi, Distt-Mohindergarh 28.434167 76.111252	Granted from 01/08/2022 - 31/03/2027	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7733 Adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
21	32 (713 of 2023)	Karan Stone Cr., Khasra no. 109/12 (7-8), 19/(7-16) Vill-Zerapur, Mohindergarh 28.319049 76.087335	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
22	33 (718 of 2023)	Shiv Sunder Grit Udyog, Kila No. 71/6, Vill-Lutafpur, Narnaul, Mohindergarh 28.042011 76.07308	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
23	324 of 2023	Karan Stone Cr., Khasra no. 109/12 (7-8), 19/(7-16) Vill-Zerapur, Mohindergarh 28.319049 76.087335	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection

24	325 of 2023	Laxmi Stone Crusher Khewat No. 190, Khatoni No. 256, M.No. 44, Kila No 14/2 (3-4), 15/2(3-19), 16/2(2-0), 17/1(3-0) at Village Kultajpur, Narnaul District-Mohindergarh 28.04574 76.05937	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7734 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
25	326 of 2023	Bajrang Stone Crusher Khewat No. 362, Khatoni No. 403, M.No. 50, Kila No. 24/1 (1-16) & 24/2 (6-12) Total 8 Kanal 08 Marla at Village Dholera, Nangal Chaudhary District Mohindergarh 27.92463 76.05933	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
26	327 of 2023	Bajrang Stone Crusher, Khewat No. 121, Khatoni No. 148, Khasra No. 53 total 260 kanal 15 marla Vill.-Faizabad, Narnaul 28.108867 76.111231	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational		Not Complying	Closed By Board
27	328 of 2023	M J ENTERPRISES, Khewat No. 6, Khatoni No. 6, M.No. 41, Kila No. 24 (6-3), 25/1 (1-14), 16/2 (0-8), 17 (1-13), Village-Kultajpur, Tehsil-Narnaul, District-Mohindergarh 28.04607 76.04958	Granted from 01/04/2023 - 31/03/2028	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

28	329 of 2023	Balaji Stone Crushing Company Khasra No. 44//6(7-8), 7 (8-0) 15/1 (1-13) Vill Garhi, PO- Khudana, Distt- Mohindergarh 28.433475 76.111387	Granted from 01/04/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7735 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
29	330 of 2023	Mahashiv Stone Crusher (DDR Stone) Khewat No. 9, Khatoni No. 21 & 22, Kila No. 19//25, 8-0, 31//5, 8-0, 30//1, 3-0 Vill-Jainpur, Narnaul, Distt-M/garh 27.90693 76.08658	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
30	331 of 2023	Banshi Stone Crusher, Rect/Kila No. 95//2, 3min east 8 min east total measuring 21 Kanal 18 marla Vill-Bayal, Narnaul, Distt-Mohindergarh 27.84928 75.97549	Granted from 01/10/2020 - 31/03/2025	-	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Deposited	Complying	NA
31	332 of 2023	Maman Grit Udyog, Khasra no. 182/209 Vill- Begopur, Tehsil- Narnaul, Mohindergarh 27.923481 76.055496	Granted from 01/10/2020 - 31/03/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

32	333 of 2023	Pooja Stone Crusher, Kila no. 53/9, 10, khewat no. 2, khatoni no. 6 Vill-Garhi, Mohindergarh 28.430789 76.111599	Granted from 01/04/2022 - 31/03/2027	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7736 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
33	334 of 2023	Bhagwati Grit Udyog, Khewat No. 110/13/8, 13/3 14-17, 18/1, 18/2 Vill-Zerapur, Mohindergarh 28.318371 76.091941	Granted from 01/04/2022 - 31/03/2027	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
34	335 of 2023	Parkash Stone Crusher, Khewat no. 173, 178, khatoni no. 198, 203 and Kila no. 57//7-8, 13/1, 14/1/1, Vill-Begopur, Narnaul 27.92508 76.0553	Granted from 01/04/2022 - 31/03/2027	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
35	336 of 2023	BHAWANI GRIT UDYOG Khewat No. 58, Khatoni No. 62, M.No. 8, Kila No. 17/1(7-11), 18/1 min East (4-09) Total 12 Kanal 0 Marla At Village-Khatoli Ahir, Tehsil-nangal Chaudhary, Distt-Mohindergarh 27.967061 76.083448	Granted from 01/04/2023 - 31/03/2028	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Deposited	Complying	NA

36	337 of 2023	Rohit Stone Crusher Company, Khewat no. 16, Khatoni no. 46,48, kila no. 8/15, 16 (16 kanal 12 Marla) Vill. Bakhrija, Narnaul, Distt. Mohindergarh 27.921571 76.053801	Granted from 01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7737 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
37	338 of 2023	Sheetla stone Crusher, Khewat no. 16, khatoni no. 46, 48 kila no. 8/15, 16) 16 kanal 12 marla Vill. Bakhrija, Narnaul, Distt. Mohindergarh 27.921098 76.052743	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board
38	339 of 2023	Dev Shri Krishna Stone Crusher, Khewat No. 31, Khatoni No. 34, M.No. 98, Kila No. 20/3 & 21 (8-16) Khewat No. 68, Khatoni No. 83, M.No. 98, K.No. 15/2 & 16(13-6), Khewat No. 70, Khatoni No. 85, M.No. 99, Kila No. 24/2 & 25 (12-0) Total 32 Kanal 12 Marla Vill-Zerapur, Distt-Mohindergarh	Granted from 06/02/2023 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
39	340 of 2023	Shiv Grit Udyog, Khasra no. 44, kila no. 24, (4-6), 2597-8) total 11 kanal 14 marla Village-Garhi, Tehsil & District-Mohindergarh 28.43308 76.11048	Granted from 01/04/2019 - 31/03/2024	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA

40	341 of 2023	SHIV SHAKTI STONE CRUSHER UNIT II, Khewat No. No. 250, Khatoni No. 277, M.No. 52, Kila No. 24 min East (7-8) & 25 min West (0-12) Total 8 Kanal 0 Marla at Village-Begopur, Nangal Chaudhary, Distt-Mohinergarh 27.927192 76.055183	Granted from 02/10/2019 - 31/03/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7738 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
41	342 of 2023	Shivalya Stone Crusher, Kila no. 57//9/2, 10/1, 10/2, 12/1 & 13/1 Vill-Begopur, Narnaul, Distt-Mohindergarh 27.92445 76.053755	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
42	343 of 2023	Shivalik Stone Crusher Co., Khewat no. 19, Khatoni no. 22, kila no. 13//3, 4/2, (4-11), (0-18) Vill-Gangutana, Nangal Chaudhary, Narnaul 27.8838 76.065491	Granted from 01/04/2022 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
43	344 of 2023	Jai Shree Shyam Stone Crusher (Formely Shivam Stone Crusher), Khewat no. 8, khatoni no. 10, kila n. 109/6/2/1(2-11)/15 (9-16), 16 (8-0) Vill-zerapur, Mohindergarh 28.324268 76.087004	Granted from 30/08/2022 - 31/03/2027	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Not Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Not Complying	Show Cause Notice issued for the non-compliance observed

44	345 of 2023	SHREE BALAJI GRIT UDYOG M.No. 56, Kila No. 13/3 (5-2), 18(2-4), 13/1 (2-15) & 13/2 (2 Marla 4 sarsai) Total 10 Kanal 3 Marla 4 Sarsai at Village-Begopur, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.924686 76.051271	Granted from 01/04/2024 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7739 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
45	346 of 2023	DHARAM GRIT UDYOG M.No. 56, Kila No. 7/1 (7-8), 7/3 & 8/1/2 (4 -12) & 7/2, 7/4, 8/1/1 (6 marla 5 sarsai) Total 12 Kanal 6 Marla 5 Sarsai at Village-Begopur, Nangal Chaudhary, Distt-Mohindergarh 27.934717 76.047124	Granted from 01/04/2024 - 31/03/2029	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
46	347 of 2023	SHREE GANPATI STONE CRUSHER, Kh. No 66, Khatoni No 70, M.No. 7, Kila No 10/2 min West-South (2-10) & M.No. 8 Kila No 6(8-0), 7 min East-South (2-0) Total 12 K.10 M. at VIII-Khatoli Ahir, Nangal Chaudhary,Distt-Mohindergarh 27.967285 76.82697	Granted from 01/04/2023 - 31/03/2028	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
47	348 of 2023	Shree Ganpati Stone Crusher, Khewat No. 12, Khatoni No. 41, Mustkil & Kila No. 8//2/2 (4-8) & 8//3/1 (5-4) Vill. Bakhrija, P.O Dholera, Narnaul Distt-Mohindergarh 27.923007 76.051278	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board

48	349 of 2023	HINDUSTHAN STONE CRUSHER, M.No. 11, Kila No. 9/2(4-0), 12/1(4-0), 12/2(3-11) & 13/1(3-11) Total 15 Kanal 02 Marla at VIII-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.965012 76.081801	Granted from 01/04/2023 - 31/03/2028	95 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7740 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
49	350 of 2023	SHREE NARAYAN STONE CRUSHER, Khewat No. 18, Khatoni NO. 20, M.No. / Kila No. 24//24 Min East (6-0) & 27//4 Min North (6-0) total 12 Kanal 0 Marla AT VIII-Khatoli Ahir, Nangal Chaudhary Distt-Mohindergarh 27.961276 76.082149	Granted from 06/06/2022 - 31/03/2027	110 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
50	351 of 2023	Ishwar Stone Crushing Co., Khewat No. 24, Khatoni No. 53, Kila No. 7/11/1(2-19, 11/2(4-5), 12, Vill. Bakhrija, Narnaul 27.92149 76.05438	Granted from 01/04/2022 - 31/03/2027	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
51	352 of 2023	Jai Durga Maa Stone Crusher, Kila no. 44/4, 5,8, 7, 8 khewat no. 87, khatoni no. 156 Vill Garhi, Mohindergarh 28.435302 76.11175	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

52	353 of 2023	SHREE OM INFRASTRUCTURE COMPANY, Khewat No. 46, Khatoni NO. 48, M.No. 23, Kila No. 21/1 Min East (2-18), 22/1/1 (4-16), 22/2/1 (1-0) & 23/1 (4-8) total 13 Kanal 02 Marla at Village Berundla, Nangal Chaudhary, Distt-Mohindergarh 27.955593	Not having valid CTO	-	-	-	-	7741	-	-	-	-	Not operational	-	Not Complying	Closed by Board
53	354 of 2023	Jai Hanuman Stone Crusher Company Kila No. 19//16(7-11), 20//11(2-8), 20(2-17) Vill-Jainpur, Tehsil-Narnaul, DisttMohindergarh 27.90704 76.087315	Granted from 01/10/2020 - 31/03/2025	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	
54	355 of 2023	JAI HIND STONE CRUSHER Khewat No. 173, Khatoni No. 202, M.No. 16, Kila No. 19 (5-12), 20/1 (0-4), 21 (0-5) & 22 (5-19) Total 12 Kanal 0 Marla at Village Lutafpur, Narnaul, DistrictMohindergarh 28.04404 76.06146	Granted from 07/07/2021 - 31/03/2026	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	
55	356 of 2023	Shree Shyam Stone Crusher Khewat No. 177, Khatoni No. 243, M.No. 43, Kila No. 9 (5-2) & 12 (3-18) at Vill-Kultajpur, Tehsil-Narnaul Distt-Mohindergarh 28.045538 76.049318	Granted from 01/04/2023 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	

56	357 of 2023	Jai Stone Crusher Co., Khwat no. 16, Khatoni no. 46- 48, Kita no. 35, Tadadi rakba 145 kanal 9 marla Vill- Bakhrija, Narnaul, Mohindergarh 27.922913 76.052799	Granted from 01/10/2020 - 31/03/2024	32 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7742 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
57	358 of 2023	Karota Stone Grinding, Khewat no. 32, khatoni no. 64, kila no. 12//20 (9-0), khewat no. 33, Khatoni no. 65, kila no. 13//16(6-12) Vill- Karota, Narnaul, Distt- Mohindergarh 27.98377 76.087415	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational		Not Complying	Closed By Board
58	359 of 2023	SHREE SHYAM BABA STONE CRUSHER M.No. 11, Kila No. 20/2 min East (2-0), 19/2 min West (2-0), 21/1/1 min East (1-11), 22 min West(2-11) & 21/1/2(1-16) Total 9 Kanal 18 Marla at Vill-Khatoli Ahir, Nangal Chaudhary, Distt- Mohindergarh 27.965519	Granted from 01/04/2022 - 31/03/2027	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
59	360 of 2023	Krishna Stone Crusher Khewat No. 365, Khatoni No. 409 (51/22) 2/19, 410 (51/23/2),1/18, 411 (51/23/1) 2/5, 412(51/23/2) 413 (51/23/2) at Vill-Dholera, Narnaul, Distt- Mohinergarh 27.923114 76.06058	Granted from 01/04/2022 - 31/03/2027	40 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Not Complying	Show Cause Notice issued for the non-compliance observed

60	361 of 2023	VINAYAK CONSTRUCTION COMPANY Khewat No. 173, Khatoni No. 202, M.No. 16, Kila No. 20/1/2 (3-19) & 21/1 (4-1) VillLutafpur, Narnaul, District-Mohindergarh 28.04617 76.512	Granted from 17/10/2022 - 31/03/2027	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7743 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
61	362 of 2023	ARIHANT STONE CRUSHER Khewat No. 235, Khatoni No. 262, M.No. 57, Kila No. 2/2 (8-0) Total 8 Kanal 0 Marla at Village-Begopur, tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.925265 76.054075	Granted from 01/04/2023 - 31/03/2028	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
62	363 of 2023	Yaduvanshi Stone Crusher, Khewat No. 98//10 (8-0), 98/11 (7-11), 99/6 (8-0), 15/1 (3-16) Vill-Zerpur, Distt-Mohindergarh 28.322281 76.086118	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational		Not Complying	CTO Revoked
63	364 of 2023	Bajrang Bali Stone Crusher, Khasra No. 98//17/2/2, 24, 109//4/1, 3/2, 18/3/2 Vill-Zerpur, Narnaul, Mohindergarh 28.320332 76.088689	Granted from 01/10/2020 - 30/09/2024	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Not Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Not Complying	Show Cause Notice issued for the non-compliance observed

64	365 of 2023	DEV SHRI KRISHNA STONE CRUSHER Khewat No. 234, Khatoni No. 261, M.No. 52, Kila No. 19 (8-0) & 18 min East (4-0) at Village-Begopur, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.92704 76.054796	Granted from CTO 01/04/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7744 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
65	365 of 2023	SHREE GANESH STONE CRUSHER, Khewat No. 73, Khatoni No. 80, M.No. 52, Kila No. 20/1 Min North (4-15), 11/1 Min South (0-12), 11/2 Min South (2-15) at Village-Begopur, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.924256 76.05244	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
66	365 of 2023	JAI SHREE SHYAM STONE CRUSHER M.No. 51, Kila No. 23/3 (1-10), 24(7-11), 16/2/2/1(0-6), 17/2/2(0-10), 17/3/2(0-3), 25/1(1- 18) & 25/2 (0-2) Total 12 Kanal 0 Marla at VIII-Dholera, Distt-Mohindergarh 27.92381 76.062573	Granted from 01/04/2023 - 31/03/2028	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
67	365 of 2023	JAI BABA SHYAM STONE CRUSHER M.No. 51, Kila No. 16/2/2/2 (1-1) & 25/3 (5-19), M.No. 52 Kila NO. 21/1/1(5-0) Total 12 Kanal 0 Marla at Village-Dholera, Tehsil-Nangal Chaudhary, District-Mohindergarh 27.923793 76.062579	Granted from 01/04/2023 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

68	366 of 2023	HARE KRISHNA STONE CRUSHER Khewat No. 14, Khatoni No. 43, M.No. 3, Kila No. 24/1(7-0), M.No. 8, Kila No. 4/1/1 (1- 19) at Village-Bakhrija, Tehsil-Nangal Chaudhary, District-Mohindergarh 27.921093 76.053368	Not having valid CTO	-	-	-	-	7745	-	-	-	-	Not operational	-	Not Complying	CTO Revoked
69	367 of 2023	SHRI HARI STONE CRUSHER Khewat No. 157, Khatoni No. 185, M.No. 16, Kila No. 9/3(2-0), 11/3 (2- 01), 12 (8-0) at Village-Lutafpur, Tehsil-Narnaul, District-Mohindergarh 28.02096 76.07285	Granted from 01/04/2023 - 31/03/2028	25 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	
70	368 of 2023	Maa Durga St. Cr. (Dalal Construction Co.), Kila no. 110-1/2 (6-0), 2/(2-0), 2(8-0) Vill-zerpur, Mohindergarh 28.324268 76.087004	Granted from 01/04/2022 - 31/03/2027	120 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	
71	369 of 2023	Shree Ram Stone Crusher, Khewat no. 13, khatoni no. 26, kila no. 19//6 (4-5), 7 (1-8), 14(1-4), 15/1 (5-0) total land (11 kanal 17 Marla) Vill.-Jainpur, Narnaul, Distt. Mohindergarh 27.9084 76.08638	Granted from 01/10/2020 - 31/03/2025	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	

72	370 of 2023	Jai Hanuman Stone Crusher, Kila no. 110//11(6-11) 110//19(7-16), 110//20(8-0) Vill-zerapur Mandola, Mohindergarh 28.318989 76.090193	Not having valid CTO	-	-	-	-	7746	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
73	371 of 2023	Jai Hind Stone Crusher, Kila no. 50 (25 kanal 3 marla) VPO- Jainpur, Narnaul, Distt. Mohindergarh 27.9084 76.08688	Granted from 01/04/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	
74	372 of 2023	Jai Shree Krishna Stone Crusher, Khewat No. 11, Khatoni No. 25, Mustil & Kila No. 16/23 (1-0), 19/3(7-14) total 16 Kanal 14 marla Vill-Jainpur, Narnaul, Mohindegarh 27.90939 76.085038	Granted from 01/04/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	
75	373 of 2023	Shree Shyam Grit Udyog, Khasra No. 24, Kila No. 16 & 17, total 16 Kanal, Vill.-Garhi, Mohindergarh 28.434559 76.11131	Granted from 01/04/2022 - 31/03/2027	55 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	-	Complying	NA	

76	374 of 2023	JC STONE CRUSHER Khwat No. 63, Khatoni No. 67, M.No. 8, Kila No. 14 min East (6-0) & 15 Min West(6-0) total 12 Kanal 0 Marla at VIII-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.967701 76.08445	Granted from 03/02/2022 - 31/03/2026	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7747 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
77	375 of 2023	JAI DURGA STONE CRUSHER, Khwat No. 5, Khatoni NO. 5, M.No. 56, Kila No. 14 (8-0) total 8 Kanal 0 Marla at Village Begopur, Nangal Chaudhary, Distt-Mohindergarh 27.92233 76.0523	Granted from 11/12/2021 - 31/03/2026	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
78	376 of 2023	SHREE GANESH STONE CRUSHER, M.No. 7, Kila NO. 1/1 Min West (4-06-1), 1/2 Min West (0-13-8) & 10 min West (5-0) 10 Kanal 0 Marla at VIII-Bakhrija, Nangal Chaudhary, Distt-Mohindergarh 27.922937 76.052345	Granted from 01/04/2020 - 31/03/2025	28 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
79	378 of 2023	Om Grit Crusher, Khwat no. 15, Khatoni no. 45, kila no. 7//8 (4-8) & 9 (9-13) total 14 Kanal 1 Marla Vill.-Bakhrija, Narnaul 27.92201 76.05493	Granted from 01/04/2021 - 31/03/2026	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

80	379 of 2023	JMD Stone Crushing Company Part I Khewat No. 5, Khatoni No. 5, Kila NO. 16//20, 21 Min Vill-Jainpur, Narnaul, Distt-Mohindergarh 27.90999 76.08419	Granted from 01/10/2020 - 31/03/2024	-	-	-	-	7748	-	-	-	-	Not operational	Deposited	Not Complying	CTO Revoked
81	380 of 2023	JMD Stone Crushing Company Part II Khewat No. 5, Khatoni No. 5, Kila NO. 16//21 Min,19//1 VillJainpur, Narnaul Distt-Mohindergarh 27.90999 76.08419	Granted from 01/04/2021 - 31/03/2026	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Deposited	Complying	NA	
82	381 of 2023	Raj Stone Crusher, Khewat no. 178, hatoni no. 203, kila no. 56/15 & 57 //1 (14 kanal 8 marla) Vill.-Begopur, Narnaul, Distt. Mohindergarh 27.92513 76.052206	Granted from 01/04/2022 - 31/03/2027	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA	
83	382 of 2023	Jayoti Stone Crusher, Khewat no. 7, Khatoni no. 36, kila no. 8//5/ 2(3-3), 6/1(3-3) & 7 (7-11) Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.92248 76.052805	Granted from 01/04/2022 - 31/03/2027	30 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA	

84	383 of 2023	SHIKOHPUR STONE CRUSHER COMPANY, Khewat No. 288, Khatoni No. 319, M.No. 62, Kila No. 7/1/2 (6-10), 15/1(1-10) at Village-Dholera, tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.922239 76.062123	Granted from 01/04/2023 - 31/03/2028	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7749 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
85	384 of 2023	Shiv Stone Crusher Khewat No. 362, Khatoni No. 402, M. No. 50, Kila No. 17 At Vill-Dholera, Nangal Chaudhary, Narnaul, Distt-Mohindergarh 27.923905 76.058892	Granted from 01/04/2022 - 31/03/2027	60 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
86	385 of 2023	Mahadev Stone Crusher Khewat No. 190, Khatoni No. 256, M.No.44, Kila No. 6/4 (4-04), 7/1(3-8), 14/2/1(0-4), 15/1(0-5) Total 8 kanal 01 Marla at Village-Kultajpur, Narnaul District-Mohindergarh 27.04327 76.06049	Granted from 22/11/2021 - 31/03/2026	20 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
87	386 of 2023	SHREE KRISHNA STONE CRUSHING MILLS, Kila No. 98(20/1), 19,18(2/2), 23(2/1) VILLAGE ZERPUR, DISTRICT-MOHINDERGARH 28.31723 76.09197	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational		Not Complying	Closed by Board

88	387 of 2023	New Haryana Stone Crusher, Khasra no. 57//8, 9/1, 13/1, Vill-Begopur, Narnaul, Distt-Mohindergarh 27.92504 76.054303	Granted from 01/04/2022 - 31/03/2027	35 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7750 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
89	388 of 2023	Yaduvanshi Grit Udyog, Khewat No. 98, Khatoni No. 165, Kila No. 8, total 58 kanal 15 Marla Vill-Garhi, Mohindergarh 28.434648 76.113061	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational		Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
90	389 of 2023	Nihal Stone crusher, Kila no. 56//6, 15 Min (15 kanal 11 Marla) Vill-Begopur, Narnaul, Distt-Mohindergarh 27.921825 76.052831	Granted from 01/04/2022 - 31/03/2027	40 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
91	390 of 2023	Jai Bajrang Bali Stone Crusher, Khasra no. 23/1/2, 10 Vill-Gangutana, Narnaul 27.8796 76.060307	Granted from 01/04/2022 - 31/03/2027	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA

92	391 of 2023	DEV STONE CRUSHER, M. No. 53, Kila No. 16/1(4-8), 16/2(3-4) & M.No. 52, Kila No. 20/2(1-12) Total 9 Kanal 4 Marla at Village-Begopur, Nangal Chaudhary, Distt-Mohinergarh 27.926883 76.052708	Granted from 01/04/2023 - 31/03/2028	45 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7751 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
93	391-392 of 2023	DEVA STONE CRUSHER, Khewat No. 6, Khatoni NO. 6, M.No. / Kila No. 7//22/1 (7-04) & 22//2/2/1 (4-16) total 12 Kanal 0 Marla at VIII-Berundla, Nangal Chaudhary Distt-Mohindergarh 27.95301 76.0788	Granted from 04/06/2022 - 31/03/2027	-	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
94	395 of 2023	NEW SIDDHI VINAYAK STONE CRUSHER, Khewat No. 37, Khatoni No. 41, M.No. 25, Kila No. 17 (8-0), 24(2-16) & 25 min West (1-4) Total 12 Kanal 0 Marla, VIII-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.960682 76.080892	Granted from 01/04/2023 - 31/03/2028	85 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
95	396 of 2023	SHREE VINAYAK STONE CRUSHER Khewat No. 8, Khata No. 8, M.No. 42, Kila No. 19/2(5-6), 20/1 (4-12), 21/2 (4-11) 22/1 (4-11) At Village-Kultajpur, Tehsil-Narnaul, District-Mohindergarh 28.04605 76.051	Granted from 01/04/2022 - 31/03/2025	65 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Deposited	Complying	NA

96	436 of 2023	LAXMI VISHNU STONE CRUSHING COMPANY, Khewat No. 10, Khatoni NO. 22, Kila No. 31//5(8-0) & 30//1(1-10), At Village-Jainpur, Tehsil-Nangal Chaudhary, District-Mohindergarh 27.909284 76.092529	Granted from 01/04/2023 - 31/03/2028	50 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	7752 Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational	Deposited	Complying	NA
97	438 of 2023	Shree Shyam Stone Crusher, KHEWAT NO. 36, KHATONI NO. 88, M.NO. 43, KILA NO. 16/2 (6-0) & 17(6-0), AT VILLAGE-GARHI, DISTRICT-MOHINDERGARH 28.43491 76.1137	Granted from 01/04/2023 - 31/03/2028	150 feet	Unit has provided covered sheds over machinery with water sprinklers for dust suppression	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Provided sufficient water sprinklers for dust suppression	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Complying	NA
98	674 of 2023	Baba Jethu Ji Stone Crusher, Khasra/ kila no. 18/19, Vill. Gangutana, Mohindergarh 27.87897 76.05966	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
99	739 of 2023	RAO STONE CRUSHER, Khewat No. 5, Khatoni NO. 5, M.No. / Kila No. 23//10/2 min West South(0-2), 23//11 Min West South (2-6), & 24//15 Min East South(7-9) total 9 Kanal 17 Marla at Vill-Khatoli Ahir, Nangal Chaudhary, Distt-Mohindergarh 27.9622 76.082992	Granted from 01/04/2022 - 31/03/2027	100 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	Operational		Not Complying	Show Cause Notice issued for the non-compliance observed

100		Karni Maa Stone Crusher, Khewat No. 144, Khatoni No. 217, M.No.71, Kila No. 3(6-9) & 8(1-11) at Village Garhi, Distt-Mohindergarh 28.42997 76.099361	Not having valid CTO	-	-	-	-	7753	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
101		Bharat Stone Crusher, Khasra/ kila no. 44//14/1, 15/2/1 Vill-Garhi, Mohindergarh 28.432936 76.111341	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board
102		Godara Stone Crusher Rect/Kila Nos. 14, 15, 6 total 17 Kanal 6 Marla Vill-Garhi, Distt-Mohindergarh 28.431036 76.103964	Granted from 28/04/2022 - 31/03/2027	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board and CTO Revoked
103		Sadashiv Stone Crusher, Kila no. 76/5, 70/21, 77/1,2 khewat no. 6, khatoni no. 18 Vill-Garhi Khudana, Distt-Mohindergarh 28.426171 76.102493	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board

104		Baba Jamna Giri Stone Crusher Khewat No. 121, Khatoni No. 190, M.No. 49, Kila No. 18 at Vill-Garhi, DisttMohindergarh 28.432052 76.111387	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
105		Balaji Stone Crusher Khewat No. 23, Khatoni No. 57, M.No. 49, Kila No. 17(8-0) at Vill-Garhi, Distt-Mohindergarh 28.433475 76.111387	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	CTO Revoked
106		Jai Hanuman Stone Crusher Khewat No. 23, Khatoni NO. 56, Kila No. 49//6/2(8-0) at Village Garhi, DistrictMohindergarh 28.43046 76.10057	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
107		SURYA STONE CRUSHER Khewat No. 23, Khatoni No. 56, M.No. 50, Kila No. 10/2/2(7-6), 11/1(7-01), 9/3/2(0-14), 12/1/1(0-8) Total 15 Kanal 09 Marla at Village-Garhi, District-Mohindergarh 28.42871 76.09925	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site

7754

108		Shree Shyam Stone Crusher, Khewat no. 19, khatoni no. 21, kila no. 109/14/2, 17 (2-0) (7-9) Vill.-Zerpur Madola, Mohindergarh 28.318989 76.090193	Not having valid CTO	-	-	-	-	7755	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
109		Maa Sherawali Stone Crushing Co Khewat No. 163, Khatoni No. 228, Kila no. 24/23, 25/3,4, 58/2/2,3,18/4/2 Vill Zerpur, Distt-Mohindergarh 28.318989 76.090193	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
110		Mungipa Stone Crusher, Khewat No. 18, Khatoni No. 20, Kila No. 12/2, 110/3, 18/3/9 village Zerpur, Mohindergarh 28.318993 76.090963	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
111		Hydel Construction Pvt. Ltd & Mobile Drill Master (Joint Venture) -HMJV Khewat No. 171, Khatoni No. 232 & 235, Mustil No. 43/1/1 (6-16), 44/4(7-11) 5 (7-11), 7/2 total 26 kanal Village-Kultajpur, Narnaul Distt-Mohindergarh 28.048477 76.064263	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection

112		Bhagwati Stone crusher, Kita no. 45//8/2/2, 9/1, 10/1, Vill. Mandlana, Distt-Mohindergarh 28.08837 76.078608	Not having valid CTO	-	-	-	-	-	7756	-	-	-	Not operational	-	Not Complying	Closed By Board
113		Deepak Construction Co., Khasra No. 211, Vill Raghunathpura, Distt. Mohindergarh 28.07425 76.07761	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed By Board
114		Shree Ganesh Stone Crusher, Khasra no. / kila no. 18/21 (7-4) & 23/1 (1-4) Vill-Gangutana, Narnaul, Distt. Mohindergarh 27.8794 76.05966	Granted from 01/10/2020 - 31/03/2025	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed By Board and CTO Revoked
115		Keshav Stone Crusher Formely Yograj Infrastructure, Plant-III, Kila no. / Khasra no. 23//11,20, Vill. Gangutana, Narnaul 27.88029 76.06203	Granted from 01/10/2021 to 31/03/2026	50 feet	Not provided adequate arrangement	Provided Wind breaking wall of adequate height & Length as per notification and also, provided telescopic chute.	Metalled road provided for Vehicular movement within premises	Wetting & Cleaning of the ground provided during inspection	Provided adequate Green belt as per report submitted by DFO, Mahendragarh	Not provided adequate sprinklers	Provided interlocking system of water sprinkler system with stone crusher machine and maintained logbook for water consumption.	-	Not operational	-	Not Complying	Show Cause Notice issued for the non-compliance observed

116		T & R Milling and Crushing Unit Mustil No. 23, Kila No. 3, Vill Gangutana, Narnaul Mohindergarh 27.877857 76.059546	Not having valid CTO	-	-	-	-	7757	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
117		T & R STONE CRUSHER, Mustil No. 23, Kila No. 2, VILLAGE-GANGUTANA, NAGAL CHODHARY, NARNUAL, Mohindergarh 27.877857 76.059546	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
118		Rathi Stone Crusher Co., Khasra no./ kila no. 30//18 Vill- Gangutana, Mohindergarh 27.8748 76.05732	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
119		Yog Milling And Crushing Unit Mustil no.-23,Kila no.-15,Village-Gangutana, Nangal Choudhary, Narnaul Mahendragarh 27.8779 76.06146	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection

120		Pooja Milling And Crushing Unit Mustil No-23, Kila No.16, Village-Gangutana, Nangal Choudhary, Distt.Mohindergarh 27.8776 76.06146	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
121		Jai Maa Kamakhaya Industries (Superb Star Promoters Private Limited), Khewat No. 20, Khatoni No. 22, Kila No. 30//3 (5-16) & 4(3-16) Vill-Gangutana, Nangal Chaudhary Distt-Mohindergarh 27.87607 76.058621	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed By Board
122		Shivam Stone Crushing Company, Khewat No. 19, Khatoni No. 21, Mustil & Kila No. 30//8/1(9-18), 9/1(0-17) Village Gangutana Tehsil Narnaul District Mohindergarh 27.875812 76.05754	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
123		Jai Mata Di Stone Crusher (FormelyJagdamba Stone Crusher), Khewat no. 16, khatoni no. 48, kila no. 7/19,20 Vill. Bakhrja, Narnaul Distt-Mohindergarh 27.90999 76.08419	Not having valid CTO	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board

7758

124		Chhawri Stone Crusher, Khewat No. 9, Khatoni NO. 38, M.No. 8, Kila No. 7/2 & 8/1 at Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.922181 76.051442	Not having valid CTO	-	-	-	-	7759	-	-	-	-	Not operational	-	Not Complying	Closed by Board
125		Krishna Arjun Buildtech Pvt. Ltd., Khewat No. 14, Khatoni No. 43, 44, Mustil & Kila No. 14 / / /11/2(3-15), 19(2-10), 22(2-18), 12(5-4), 13/2(3-1) Vill-Bakhrija, Narnaul, Distt-Mohindergarh 27.9193 76.054323	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	CTO Revoked
126		KSY Grit Udyog, Khewat no. 182, khatoni no. 209, 57//14-1(0-17), 15/1(4-5), 15/2 (1-5), Total 6 kanal 7 Marla & 57//14/2(3-2), 57//7(5-18) total 9 kanal 0 marla Vill.-Begopur, Narnaul 27.9247 76.056188	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
127		Universal Stone Crusher, Khewat No. 16, Khatoni No. 29, Kila No. 19//4(2-16), 6(4-5), 7(8-0), 14(8-0), 15/1(5-0), 17(7-11) Vill-Jainpur, Distt-Mohindergarh 27.90875 76.08591	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection

128		Vishal Stone Crusher, Khewat no. 13, khatoni no. 26, Kila no. 19//14, min (4-5) & 17(7-11) Vill.-Jainpur, Narnaul, Distt. Mohindergarh 27.907128 76.086277	Not having valid CTO	-	-	-	-	7760	-	-	-	-	Not operational	-	Closed of its own and found closed during inspection	Closed of its own and found closed during inspection
129		Shree Balaji Stone Crusher, Kila no. 19/2, 9, 10, 11/1, khewat no. 4,5,6 Village Jainpur, Narnaul Distt.- Mohindergarh 27.90913 76.08468	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	Closed by Board
130		Vinayak Stone Crusher, Khasra no. 82 Min (24-0) VPO- Jainpur, Narnaul, Distt-Mohindergarh 27.9099 76.09248	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site
131		Maa Durga Stone Crusher, Khasra No. 11/1/2(3-8), 11//2 (7-11) Vill-Khatoli Ahir, Distt-Mohindergarh 27.96628 76.08047	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Unit found dismantled from the site	Unit found dismantled from the site

132		SHRI VINAYAK STONE CRUSHER, Khewat No. 10, Khatoni No. 10, M.No. 28, Kila No. 1 (8-0) & 10 min North (4-0) Total 12 Kanal 0 Marla at VIII-Berundla, Tehsil-Nangal Chaudhary, Distt-Mohindergarh 27.954878 76.080504	Not having valid CTO	-	-	-	-	7761	-	-	-	-	Not operational	-	Not Complying	Closed by Board
133		K S Y BUILDCON, Khewat No. 50, Khatoni NO. 72, M.No. 9, Kila No. 15/2/2 (2-17), 16/2 Min West (5-14) & 17/1 (0-9) total 9 Kanal 0 Marla at Village Khatoli Jat, Nangal Chaudhary, Distt-Mohindergarh 27.97287 76.08708	Not having valid CTO	-	-	-	-	-	-	-	-	-	Not operational	-	Not Complying	CTE Revoked